



## NL#1107: Part Status Change

Date: October 14, 2004

**MT. VERNON, MO**

Phone:  
800-753-0050  
Fax:  
417-466-3964

Customer Notice – Please be advised of the following part status changes.

The following Reyco Suspension kits are being moved from “Phase-Out” (PHO) to “Obsolete” (OBS) status.

Part Number	Description	Model Affected	Superseded By
TK10586	Tandem Axle Rebushing Kit	Series 101	(4) TK19166
TK11988	Tandem Axle Rebushing Kit	101A	N/A

**INTERNATIONAL**

Phone:  
1-417-466-1028  
Fax:  
1-417-466-1052

Copies of this newsletter can be obtained by calling your District Sales Manager or one of our Customer Service Account Managers.

For more information about the full line of ReycoGranning truck and trailer suspensions contact:

Mark S. Thomson  
Tuthill Transport Technologies  
1205 Industrial Park Drive  
Mt. Vernon, MO 65712  
800-753-0050  
417-466-1061  
[mthomson@tuthill.com](mailto:mthomson@tuthill.com)

Visit our website at [www.reycogranning.com](http://www.reycogranning.com)

