

## LOCATIONS

### MT. VERNON, MO

Phone:  
800-753-0050  
Fax:  
417-466-3964

### BROOKSTON, IN

Phone:  
800-255-7824  
Fax:  
219-279-2390

### GRIMSBY

Phone:  
800-811-4011  
Fax:  
905-945-5906

See us at:

reycogranning.com

NL # 1116

REF: ECR # 15069, 15230, 15272, 15407, 15468, 15486, 15518 and 15520.

Effective: Immediately

Customer Notice – Please be advised of the following part status changes.

The following Reyco Suspension parts are being moved to “Obsolete” (OBS) status, due to inactivity.

1505-01	Model 86/88	1292701	Model 81	0106-06 superceded by 16095-01	Model 86/88
1039-01	Model 86/88	1292700	Model 81	2240501 superceded by 2240701	Model 79KB
1039-02	Model 86/88	22594-01	Model 1200	2240502 superceded by 2240702	Model 79KB
1039-03	Model 86/88	22595-01	Model 1200	0150-00 superceded by 0923001	Various Models
1039-04	Model 86/88	22595-02	Model 1200		
1039-22	Model 86/88	22595-03	Model 1200		
1039-99	Model 86/88	22595-04	Model 1200		
1040-01	Model 86/88	1969732	Model 1200		
1040-02	Model 86/88	19790-01	Model 86AR		
1040-03	Model 86/88	701582-01	Model 550PM		
1040-22	Model 86/88	701583-01	Model 550PM		
1040-99	Model 86/88	701584-01	Model 550PM		
1350-00	Model 86/88	2012001	Various Models		
1351-00	Model 86/88				

**2171903** (When ordering TK22433, part # 2171903 has been replaced by, 2x 704880-01, 8x 1735401 and 2x 23519-01)

If you have any questions, feel free to contact your District Sales Manager, or Customer Service Account Manager.