

PRODUCT BULLETIN #PB2044_Rev B

DATE: April 17, 2001
SUBJECT: Material / Welding Change
EFFECTIVE: Immediately

REF: SPACER BLOCKS
Axle Seat Spacers

Dear Valued Customer,

Effective January 2000, Product Bulletin #2022 was issued announcing a change in spacer blocks.

Product Bulletin #2022

Reyco/Granning Suspensions would like to introduce the implementation of ductile iron spacers to the axles on all steel spring trailer suspension models. The new ductile spacers will be released January 1, 2000 and will replace all cast steel spacers. The old cast steel spacers will be available upon request only.

This change is due to our continuous efforts to reduce weight and will not affect fit, form or function. ***The ductile iron spacers will directly replace the cast steel spacers and cannot be welded.***

	<u>Cast Steel Spacer</u>	<u>Ductile Iron Spacer</u>
1"	T7716	24081-01
1 ½"	T7654	24082-01
2"	T7655	24083-01
2 ½"	T7674	24084-01

Please note that ½" spacer blocks (PN T7555) remain manufactured items, fabricated from ½" steel plate. These blocks do not have the "spring locator studs" and need to be welded.

Thank you for your patience and understanding.

For more details, please contact your District Sales Manager.

Reyco
Granning
SUSPENSIONS