

PRODUCT BULLETIN #PB-CA100902

DATE: October 9, 2002

**REF: AR Series Suspension
23AR / 25AR / 30AR**

Dear Valued Customers:

Please be advised that we are improving the disc spring washer found in our 23AR, 25AR and 30AR air ride suspensions.

The effectivity date of this change is mid October 2002.

On or about the 21st of October, all suspensions will be shipped with a new style disc spring washer. Below are visual examples so that your installation teams will not be surprised or think that there has been an error or wrong part shipped to you.

The part number for this component does not change.

The installation procedure and torque value will not be affected. Please continue to install as per our current installation instructions.



OLD STYLE



NEW STYLE

Call us today to request sales literature or a visit from one of our experienced representatives. We, at TUTHILL TRANSPORT TECHNOLOGIES, thank you for your continued support.



TUTHILL
Transport Technologies



CLASS40K

CLASS50K

IN CANADA
IN USA
International Tel
International Fax

1.800.811.4011
1.800.753.0050
1.417.466.1040
1.417.466.1052